Pressure Transmitter

Cable Type

- 0 to 1...1,000bar
- Dry/Wet media
- Superior Long term Stability
- **■** Temperature Compensated
- **Linear Amplified Output**
- Excellent Repeatability & Hysteresis
- **EMI/RFI Protection**

P-77 series Long term minimization of these errors is maintained after millions of full scale overpressure cycles, making electronic set point virtually drift-free. Use of ceramic materials in the sensing element or silicon MEMS strain gage elements glass bonded to stainless steel diaphragm and its mounting provides excellent resistance to most liquids and chemicals. Ruggedness and reliability are also enhanced by a stainless steel housing to resist corrosion pressure sealing for media compatibility is provided by selection of welding Sealing type. metal sensing element contains and integral, reliable, solid state, custom hybrid circuit signal conditioner. This circuit is digital interface can be used for a simple PC-controlled calibration procedure, in order to program a set of calibration coefficients into an on-chip EEPROM and without the cost overhead associated with trimming by external devices or a laser.




TYPICAL APPLICATIONS

- ✓ Transmissions
- ✓ Water management
- ✓ Air conditioning and refrigeration
- ✓ Pneumatic and hydraulic controls
- ✓ Pump and compressors
- ✓ Level / Depth instrumentation

Physical Data [Custom Ranges and Compound Ranges Available]									
Gauge Pressure	Unit	Over Pressure	Burst						
♦ 5, 10, 15, 20, 35, 50	bar	♦3 x F.S.	♦ 5 x F.S.						
◆ 100, 250, 300,600,1000	bar	♦ 2 x F.S.	♦ 3 x F.S.						

General SPEC								
Characteristic	P-77(V)	P-77(A)						
Pressure Range	0 to 1300bar							
Power Supply	[Voltage] 5/12/24VDC	[Current] 5/12/24VDC						
Output	[3 Wire] 0.5 to 4.5VDC 1 to 6VDC	[2 Wire] 4 to 20mA						
Operating Temp. Range	-40 to 1	135℃						
Compensated Temp. Range	-30 to 125 ℃							
Accuracy	±1.0 %F.S (Option: ±0.5 %F.S)							
Non-linearity	±0.1%							
Hysteresis and repeatability	±0.03%	typical						
Body Material	SUS3	304						
ASIC Diagram	lemp Fro	Power SCA, SCA, SCA, SCA, SCA, SCA, SCA, SCA,						



			How to	oraer				
P - 77								
1) Output type	<u> </u>			<u> </u>				
Voltagetype	V	I	I	1	1	1	1	1
Current type	Α	I	I	1	1	1	1	1
?) Kind of pressure		I	I	1	1	1	1	1
Absolute pressure		Α	ı	1	1	ı	1	1
Gauge pressure		G	ı	1	1	I	1	1
3) Pressure range			I	1	1	1	1	1
			005	1	1	1	1	I
0 to 10 bar			010	1	1	1	1	1
0 to 15 bar			015	1	1	1	1	I
0 to 20 bar			020	1	1	1	1	1
0 to 35 bar			035	1	1	1	1	1
0 to 50 bar			050	1	1	1	1	1
0 to 100 bar			100	1	1	1	1	1
0 to 250 bar			250	·	i	·	·	·
0 to 300 bar			300	·	i	· I	·	· i
0 to 600 bar			600	·	i	i	·	·
0 to 1000bar			1K0	·	i	i	·	i
Other on request			Z	·	· I	i	· I	· I
1) Output signal			_	·	· I	i	· I	·
0.5 to 4.5 VDC				V1	·	i	·	·
1 to 6 VDC				V2	·	i	·	·
4 to 20mA				A				
Other on request				Z				
5) Supply Voltage				_				
					5			
					12			
					24	'		
Other on request					Z	'		'
i) Process connection					_	'		'
PF1/4"						F14	'	'
PT1/4"						T14	'	'
Other on request						Z	'	'
7) Seal material							'	'
							S	'
NBR								'
							N	ı
Viton							V 7	1
Other on request 3) Connection type							Z	I I
Circular cable type								, C
Other on request								z
other on request	-		_	_	_		_	_